

## *Ultrasonic Welding Troubleshooting Guide*

PROBLEMS	PROBABLE CAUSES	SOLUTIONS
Overweld	Too much energy into the part  Excessive joint size.	Reduce pressure, gauge, and/or trigger. Reduce weld time/energy. Change to lower ratio booster to reduce amplitude. Slow down stroke. Use power control (last resort). Change to lower gain horn if lowest booster is already in use.  Reduce joint area, energy director or shear.
Underweld	Insufficient energy into the part.  Energy loss into fixture. (If fixture is urethane.)  Presence of mold release.	Increase pressure, gauge and/or trigger. Increase weld time/energy. Use higher ratio booster to increase amplitude, if horn allows. Change to higher gain horn if highest booster is already in use.  Change fixture to rigid material.  Eliminate use or clean parts after molding.
Non-uniform weld around the joint	Warped part(s).  Energy director varies in height.  Lack of parallelism between horn, fixture and part.  Wall flexure.  Knock-out pin location in joint area.  Insufficient support in the fixture.  Part tolerance.  Improper alignment.	Check part dimensions. Check molding conditions. Use higher trigger pressure.  Redesign energy director to ensure uniform height. Check molding conditions.  Shim fixture where necessary. Check part dimensions. Check part fit with horn using carbon paper.  Add internal ribs to part. Modify fixture to prevent outward flexure.  Move knock-out pin location from joint area. Make sure knock-out pin marks are flush with surface. Improve support in critical areas. Change to a rigid fixture. If large sections of urethane are deflecting, add rigid backup or use higher durometer urethane  Tighten part tolerances. Check molding conditions.  Check for part shifting during welding. Check provisions for alignment in mating parts. Check for parallelism of horn, part, and/or fixture.



PROBLEMS	PROBABLE CAUSES	SOLUTIONS
Non-uniform weld around the joint (continued)	<p>Lack of intimate contact around joint area.</p> <p>Non-uniform horn contact.</p> <p>Mold release.</p> <p>Fillers.</p> <p>Moisture in joint area.</p>	<p>Check part dimensions.</p> <p>Check tolerances.</p> <p>Check for knock-out pin marks in the joint area.</p> <p>Check for misalignment of mating halves.</p> <p>Check for sinks.</p> <p>Check part fit with horn using carbon paper.</p> <p>Check fit of part to horn.</p> <p>Check for proper support in fixture.</p> <p>Clean mating surfaces.</p> <p>If mold release is required, use a paintable/printable grade.</p> <p>Check molding conditions.</p> <p>Reduce the amount of filler.</p> <p>Dry parts as required.</p>
Inconsistent weld results part-to-part	<p>Mold release.</p> <p>Part tolerances.</p> <p>Cavity-to-cavity variations.</p> <p>Regrind/degraded plastic.</p> <p>Changes in line voltage.</p> <p>Drop in air line pressure.</p> <p>Filler content too high.</p> <p>Non-uniform distribution of filler.</p> <p>Wrong joint design.</p> <p>Degraded material.</p> <p>Poor part fit.</p> <p>Incompatible materials or resin grades.</p> <p>Moisture in molded part. (Usually nylon parts.)</p>	<p>Clean mating surfaces.</p> <p>If mold release is required, use a paintable/printable grade.</p> <p>Tighten part tolerances.</p> <p>Check part dimensions.</p> <p>Check molding conditions.</p> <p>Run statistical study to see if a pattern develops with certain cavity combinations.</p> <p>Check part tolerances/dimensions.</p> <p>Check for cavity wear.</p> <p>Check molding conditions.</p> <p>Centralize gate location.</p> <p>Check with molder for percentage of regrind.</p> <p>Check molding conditions.</p> <p>Reduce percentage of regrind.</p> <p>Improve quality of regrind.</p> <p>Use an in-line voltage regulator.</p> <p>Raise compressor output pressure.</p> <p>Add surge tank with a check valve.</p> <p>Reduce percentage of filler.</p> <p>Check molding conditions.</p> <p>Change type of filler, i.e., short- to long-glass fibers.</p> <p>Check molding conditions.</p> <p>Check mold design.</p> <p>Redesign joint, check with Branson personnel.</p> <p>Check molding conditions.</p> <p>Check part dimensions.</p> <p>Check part tolerances.</p> <p>Check molding conditions.</p> <p>Check Branson Technical Information Sheet PW-1.</p> <p>Check with resin supplier.</p> <p>Check with Branson Applications Lab.</p> <p>Receive parts dry-as-molded, bagged and sealed.</p> <p>Dry parts, then weld.</p>

PROBLEMS	PROBABLE CAUSES	SOLUTIONS
Marking	<p>Horn heats up.</p> <p>Localized high spots in part.</p> <p>Raised lettering.</p> <p>Improper fit of part to fixture.</p> <p>Aluminum oxide (from horn).</p> <p>Horn doesn't fit part correctly.</p> <p>Improper horn contour.</p> <p>Weld cycle is too long.</p> <p>Lack of parallelism.</p>	<p>Check for loose stud. Check for loose tip. Reduce weld time. Cool horn with ambient or refrigerated air. Check coupling between horn and booster. Visually check for cracked horn. If horn is titanium, change to chrome-plated aluminum. If horn is steel, reduce amplitude.</p> <p>Check part dimensions. Check fit of horn to part in fixture. Use polyethylene film between horn and part.</p> <p>Relieve horn. Use recessed lettering where possible.</p> <p>Check for proper support. Redesign fixture. Check for cavity-to-cavity variations.</p> <p>Chrome-plate horn and/or fixture. Use polyethylene film between horn and part.</p> <p>Check part dimensions. Obtain a new horn. Check for cavity-to-cavity variations.</p> <p>Check part size. Check for cavity-to-cavity variations.</p> <p>Reduce weld time by adjusting amplitude and/or pressure. Adjust dynamic triggering pressure.</p> <p>Check for parallelism between horn, part, and fixture. Check horn/part fit. Check part/fixture fit. Shim fixture where necessary.</p>
Flash (see also non-uniform welding)	<p>Energy director too large.</p> <p>Shear interference too great.</p> <p>Weld time too long.</p> <p>Non-uniform joint dimensions.</p> <p>No joint design (butt surfaces).</p>	<p>Reduce size of energy director. Reduce weld time. Reduce pressure. Use textured surface.</p> <p>Reduce amount of interference.</p> <p>Reduce weld time.</p> <p>Redimension joint. Check molding conditions.</p> <p>Incorporate proper joint design, check with Branson personnel.</p>
Misalignment of welded assembly	<p>Lack of proper alignment feature between mating parts.</p> <p>Improper support in fixture.</p> <p>Wall flexure.</p> <p>Joint design improper dimension.</p> <p>Part tolerance/poor molding.</p> <p>Overwelding.</p>	<p>Add alignment feature to the mating part halves (i.e., pins and sockets). If possible, design means of alignment into the tooling.</p> <p>Redesign fixture for proper support. Shim fixture where necessary. If large sections of urethane are deflecting, add rigid backup.</p> <p>Add ribs or gussets to part. If large sections of urethane are deflecting, add rigid backup.</p> <p>Redimension parts.</p> <p>Tighten part tolerances. Check molding conditions.</p> <p>Reduce weld time/energy/pressure.</p>

# BRANSON

PROBLEMS	PROBABLE CAUSES	SOLUTIONS
Internal components damaged during welding	Excessive amplitude.  Long weld time.  Too much energy into the part.  Components improperly mounted, i.e., mounted too close to joint area, etc.  Location of components.	Reduce amplitude by changing to a lower gain booster. Investigate the use of 40 kHz equipment.  Reduce weld time by adjusting amplitude and/or pressure. Adjust dynamic triggering pressure.  Reduce amplitude. Reduce pressure. Reduce weld time/energy. Use power control. Investigate the use of 40 kHz equipment.  Make sure internals are properly mounted. Isolate internal components from housing. Move components away from areas of high energy concentration. Use nodally-mounted device to dampen energy locally.  Components should be in fixture part.
Melting/fracture of part sections outside of joint.	Sharp internal corners.  Excessive amplitude.  Long weld time.  Internal stress.  Knit/flow lines.  Improper molding conditions.  Gate located near joint.	Radius all sharp corners.  Reduce amplitude by changing to a lower gain booster. Reduce horn amplitude if lowest booster is already in use.  Reduce weld time. Increase amplitude (if horn/booster restrictions allow). Increase pressure. Adjust dynamic triggering pressure.  Check molding conditions. Check part design.  Check molding process parameters.  Check molding conditions.  Move gate area away from joint.
Diaphragming	Excessive amplitude.  Long weld time.  Gate location.    Horn type and/or placement.    Thin wall section.	Reduce amplitude.  Reduce weld time by increasing amplitude and/or pressure.  Check gate placement. Check molding conditions. Change shape of gate. Add stiffening ribs to the part. Increase thickness of material on the underside of the gate area.  Change horns. Check for horn/part fit. Use a horn with a nodal plunger. Add vent hole in horn.  Increase wall thickness.
Internal parts welding	Internal parts same material as housing.	Change material of internal parts. Lubricate internals.